


**FIGURE 10.2** Landslide Risk Zones



Raimi + Associates 2023 | Data Source: City of Thousand Oaks, County of Ventura, County of Los Angeles; Department of Conservation, California Geological Survey, 2000

- |   |             |   |             |   |                      |   |                              |
|---|-------------|---|-------------|---|----------------------|---|------------------------------|
|  | City Limits |  | Major Roads |  | Landslide Zones      |  | Unincorporated Counties Land |
|  | City Sphere |  | Freeways    |  | Parks and Open Space |  | Adjacent cities              |